#### 1999: 737-200 Buenos-Aires

- General context
  - Commercial flight taking off from Buenos Aires-Cordoba
  - 104 POB
  - Night
  - Clear sky
- Operational context
  - Take off
  - An alarm sounds...



#### 1999: 737-200 Buenos-Aires

- At take-off an alarm may sound if the aircraft is not properly configured:
  - 1. Flaps (1 to 15)
  - 2. Slats in the take-off position
  - 3. Parking Brake lever in the OFF position
  - 4. Speed brakes lever is DOWN
  - 5. Stabilizer trim not within the green band

## 1999: 737-200 Buenos-Aires (con'd)

#### CVR recording



- On the CVR tape:
  - Recognize the thrust increase for take-off
  - Recognize all call out:
    - ♦ 80 kt
    - ▶ V1
    - Rotation
    - ▶ V2
  - Trim clicks
  - And a horn
  - Until the crash...

## 1999: 737-200 Buenos-Aires (con'd)

- Sound on the CVR recording:
  - TAKE-OFF CONFIGURATION WARNING HORN
  - For 37 seconds...
  - From the power up until... the crash
  - This warning horn was totally ignored by both crew

# 1999: 737-200 Buenos-Aires (con'd)

An





## 1999: 737-200 Buenos-Aires (end)

#### Consequences

 Airplane crushed through a fence, bounced across a busy highway, and skidded across a golf driving range exploding into flames.

- 79 killed
- Aircraft destroyed
- 3 cars crushed (1 killed)



